



**Inspection No:** INSP-21348  
**Inspection Type:** General NSPIRE Inspection

**Property:** (IL068000001) - 217 N MAIN Street, GRAYVILLE, **Inspection Date:** 8/27/2024  
 IL, 62844, US  
**Inspector:** ,

**Escort Name:** Pam Deig  
**Property Type:** SD  
**Inspection Start Date/Time:** 8/27/2024 9:03 AM

**Escort Email:** whitecountyha@gmail.com  
**Scattered Site:** Yes  
**Inspection End Date/Time:** 8/27/2024 4:29 PM

**Present During Inspection:** Yes

**Preliminary Scores**

**Preliminary Inspection Score:** 99  
**Preliminary Calculated Score:** 99  
**Preliminary Units Threshold:** 1.15  
**Preliminary Property Threshold:** 1  
**Preliminary Projected Inspection Score:** 99  
**Preliminary Non-Scored Symbols:** \*

**Final Scores**

**Final Inspection Score:** 99  
**Final Calculated Score:** 99  
**Final Units Threshold:** 1.15  
**Final Property Threshold:** 1  
**Final Projected Inspection Score:** 99  
**Final Non-Scored Symbols:** \*

**Building/Unit Inspection Data**

Type	Inspection		
	Property Total	Sample Size	Total Units Inspected
Buildings	59	24	24
Units	115	26	26

**Occupancy Information**

Occupancy Rate(%)
90

**Deficiency Summary**

Inspectable Area	Life-Threatening	Severe	Moderate	Low
Inside	0	0	0	0
Outside	0	0	1	0
Units	2	0	9	1

**Scoring Summary**

Inspectable Area	Life-Threatening	Severe	Moderate	Low
Inside				
Outside				
Units				
Total				
			Overall	